

Inspection Photos

Operator: Paradox Upstream
API: 113-06178
Date: 7/15/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing and is comprised of grasses and shrubs such as western wheatgrass, crested wheatgrass, rubber rabbitbrush. Flowering musk thistles (~50) need to be controlled.



Photo 3. View of unused parts and equipment stored on the well pad.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of big sagebrush, blue grama, and sand heath.