

Inspection Photos
Operator: Paradox Upstream
API: 113-06203
Date: 7/16/2020



Photo 1. View of the project area from the southeastern edge facing center. Location is infested with diffuse knapweed.



Photo 2. Closeup view of diffuse knapweeds within the project area.




Photo 3. View of the western project area facing southward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of big sagebrush, blue grama, and sand heath.