

Inspection Photos

Operator: Paradox Upstream
API: 113-06244
Date: 7/13/2020



Photo 1. View from the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward.



Photo 3. View erosional channeling within the southeastern project area. Channel is approximately 2-3 feet wide and deep.



Photo 4. View of another erosional channel within the southeastern project area needing stabilization.



Photo 5. View of halogeton weeds on observed on the well pad. Approximately 75 individuals observed.



Photo 6. View of reference area comprised of blue grama, sagebrush shrubland.