

Inspection Photos
Location Name: SMITH-WOLTER 1
API#: 05-067-07236
INSP. #: 695103016



Colorado Oil & Gas Conservation Commission
37.23958, -107.65735, 2243.0m, 102°
2020/07/23 07:14:00



PHOTO 2: WELL SIGN

PHOTO 1: LOCATION

Inspection Photos

Location Name: SMITH-WOLTER 1

API#: 05-067-07236

INSP. #: 695103016



PHOTO 3: NOXIOUS WEEDS (THISTLE) ON AND AROUND LOCATION AND IN INTERIM RECLAMATION AREA. REMOVE NOXIOUS WEEDS, COMPLY WITH RULE 1003.f. CA DATE 7-27-20.

PHOTO 4: ANOTHER IMAGE OF CA FROM PHOTO 3.