

Inspection Photos
Location Name: Badding 15-35
Location ID: 319411



Photo 1 WH/sign



Photo 2 WH/sign

Inspection Photos
Location Name: Badding 15-35
Location ID: 319411



Photo 3 WH/sign




Photo 4 WH/sign

Inspection Photos
Location Name: Badding 15-35
Location ID: 319411



Photo 5 WH/sign



Photo 6 WH/sign

Inspection Photos
Location Name: Badding 15-35
Location ID: 319411



Photo 7 Ag fence in disrepair



Photo 8 unused equipment/trash

Inspection Photos
Location Name: Badding 15-35
Location ID: 319411



Photo 9 unused equipment/trash