

Inspection Photos
Location Name: Badding Tank Battery 35 SWSE
Location ID: 462965




Photo 1 TB/signs

Photo 2 TB

Inspection Photos
Location Name: Badding Tank Battery 35 SWSE
Location ID: 462965



Colorado Oil & Gas Conservation Commission
 17119 9th St, Fort Lupton, CO 80621, USA
 40.08998, -104.74159, 5021.4ft, 156
 07/22/2020 12:04:20



Colorado Oil & Gas Conservation Commission
 17119 9th St, Fort Lupton, CO 80621, USA
 40.08998, -104.74159, 5031.7ft, 93°
 07/22/2020 12:04:49

Photo 3 Gas Meter Run

Photo 4 Card in meter house indicates current calibration

Inspection Photos

Location Name: Badding Tank Battery 35 SWSE

Location ID: 462965



Photo 5 ECDs

Photo 6 Horizontal Heated Separators

Inspection Photos

Location Name: Badding Tank Battery 35 SWSE

Location ID: 462965



Photo 7 Unused Horizontal Heated Separator