

Inspection Photos
Location Name: Meredith #1
Location ID: 331163



Photo 1 WH sign



Photo 2 WH, pump jack is not connected to well.

Inspection Photos
Location Name: Meredith #1
Location ID: 331163




Photo 3 PJ not connected to WH, Trash by base



Photo 4 trash, no motor connected to PJ.