

Inspection Photos
Location Name: Reserve 3-65 26 1H
Location ID: 001-09779



Pic 1



Pic 2

Inspection Photos

Location Name: Reserve 3-65 26 1H

Location ID: 001-09779



Pic 3 inadequate netting.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources