

Inspection Photos
Operator: Kinder Morgan
API: 083-06704
Date: 7/9/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with crested wheatgrass and western wheatgrass.




Photo 3. View of Russian knapweeds blooming within the southern project area. Approximately 100 individuals observed.



Photo 8. View of reference area vegetation comprised of pinyon and juniper woodland, with sagebrush, yucca, antelope bitterbrush, Indian ricegrass, and Navajo tea in the understory.