

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2020

Submitted Date:

07/25/2020

Document Number:

688308262

**FIELD INSPECTION FORM**

Loc ID 416953 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10706  
Name of Operator: D90 ENERGY LLC  
Address: 202 TRAVIS STREET #402  
City: HOUSTON State: TX Zip: 77002

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Koehler, Bob		bob.koehler@state.co.us	
Quint, Craig		craig.quint@state.co.us	
Oakes, Kevin	713-227-0391	kevin@d90energy.com	Designated Agent
James, Cole	719-892-0378	cj0378@hotmail.com	Pumper
Vincent, Kenny	(337) 654-9404	kvincent@reagan.com	Principal Agent

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416957	WELL	IJ	10/20/2017	DSPW	073-06413	JOHN CRAIG 7-2	SI

**General Comment:**

Reinspection, UIC MIT, passed

**Inspected Facilities**

Facility ID: 416957 Type: WELL API Number: 073-06413 Status: IJ Insp. Status: SI

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

**UIC Routine**

Inj./Tube: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: CDHL

TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: 07/08/2019

Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: Verification of Repairs Tbg psi: -11 Csg psi: 0 BH psi: Down to

Insp. Status: Pass

Comment: Extreme Heat Truck MIRU  
0 min 389 psi  
5 min 385 psi  
10 min 381 psi  
15 min 381 psi  
After test, casing 0 psi, tubing -11 psi (-11 throughout test), Brhd Down to 0 psi

Corrective Action: Operator to submit Form 21 to COGCC database within 10 days. Date: 08/07/2020

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI for test

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688308263	D90 Energy John Craig 7-2 well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5210498">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5210498</a>
688308264	D90 Energy John Craig Extreme Heat truck	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5210499">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5210499</a>
688308266	Form 21	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5210500">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5210500</a>