

Inspection Photos
Operator: BP America
API: 067-09327
Date: 7/23/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing with crested wheatgrass, western wheatgrass, and sand dropseed.



Photo 3. View of erosional channel forming, approximately 2 feet wide and 1 foot deep within the southern project area.



Photo 5. View of reference area comprised of sagebrush shrubland with understory of grasses such as western wheatgrass, crested wheatgrass, and Indian ricegrass.