

BP L48 San Juan



## V2 Compliance Follow Up Form

18148065743

**Reference Number:**

**Form Name:**

**Submitter Name:**

**Submission Date:**

**Location:**

20200713-18148065743

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Jul 13, 2020 4:28:25 PM MDT

1060 Co Rd 514, Ignacio, CO 81137, USA

Jul 13, 2020 4:27:22 PM MDT [ [View Map](#) ]

## INFORMATION

### Section 1

**Name** kenneth.canterbury@crossfire-llc.com

**Date** Jul 10, 2020

**Well Name** MCCAWE GAS UNIT C 2

**API Number** 50670881000

**Select State** Colorado

**Work type** COGCC Inspection AR

**Action Complete** Compliance Inspection Actions

Clean Up Land Owner Debris

Clean Up Contaminated Soils

**Photo of first corrective action completed**



Completed work description Corrective  
Action 1

Compliance

Photo of second corrective action completed



**Completed work description of corrective action 2**

Cleaned up stains

**Photo of third corrective action completed**





**Completed work description of corrective action 3**

Cleaned up stains

**Photo of fourth corrective action completed**



**Completed work description**

New well sign

**Completed work description of corrective action 4**

Cleaned up stains

**Additional photos**



**Completed work description**

Compliance, cleaned up stains, and cleaned up trash

**Summary of all work completed**

Compliance, cleaned up stains , and picked up trash