

Inspection Photos
Location Name: Kodak South FD Pad 28-222HN
Location ID: 306149




Photo 1: Wellhead Sign



Photo 2: Equipment removed

Inspection Photos
Location Name: Kodak South FD Pad 28-222HN
Location ID: 306149



Photo 3: Equipment removed



Photo 4: Unused equipment

Inspection Photos

Location Name: Kodak South FD Pad 28-222HN

Location ID: 306149



Photo 5: Wellhead Sign



Photo 6: Stained soil

Inspection Photos
Location Name: Kodak South FD Pad 28-222HN
Location ID: 306149



Photo 7: Stained soil



Photo 8: Wellhead Sign

Inspection Photos
Location Name: Kodak South FD Pad 28-222HN
Location ID: 306149



Colorado Oil and Gas Conservation Commission
40.4527, -104.86403, 1427.0m, 44°
Jul 27, 2020 14:24:00

Photo 9: Stained soil



Colorado Oil and Gas Conservation Commission
40.45269, -104.86405, 1426.7m, 16°
Jul 27, 2020 14:24:08

Photo 10: Stained Soil (different angle)

Inspection Photos
Location Name: Kodak South FD Pad 28-222HN
Location ID: 306149




Photo 11: Wellhead Sign



Photo 12: Stained soil

Inspection Photos

Location Name: Kodak South FD Pad 28-222HN

Location ID: 306149



Photo 13: Wellhead Sign



Photo 14: Stained soil

Inspection Photos

Location Name: Kodak South FD Pad 28-222HN

Location ID: 306149



Photo 15: Wellhead Sign displayed



Photo 16: Stained soil removed