

Inspection Photos

API: 055-06219

Operator: PETROGLYPH OPERATING CO INC

Inspection Date: 7/27/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06219 | Date: 7/27/2020

Inspection Photos



Photo 1. Facing southeast along the access road. Rock check dams were installed along the side of the road but have since failed. The rock has been displaced as shown by arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 7/27/2020

Inspection Photos



Photo 2. There is signs of stormwater flowing down the road causing erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 7/27/2020

Inspection Photos



Photo 3. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 7/27/2020

Inspection Photos



Photo 4. Facing southeast at the location..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 7/27/2020

Inspection Photos



Photo 5. Facing south at the east side of the location. The vegetation appears to be establishing well in areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 7/27/2020

Inspection Photos



Photo 6. Facing southwest toward the location. The vegetation appears to be establishing well in areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 7/27/2020

Inspection Photos



Photo 7. Facing toward the fill slope. The plastic netting remains along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 7/27/2020

Inspection Photos



Photo 8. Facing east toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 7/27/2020

Inspection Photos



Photo 9. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06219 | Date: 7/27/2020