

Inspection Photos  
Operator: BP America  
API: 067-06989  
Date: 7/23/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing with smooth brome, western wheatgrass, and sand dropseed.





Photos 3/4. View of unused equipment stored within the project area.



Photo 5. View of reference area comprised of mixed sagebrush shrubland with pinyon and juniper trees adjacent to irrigated grass fields.