

Inspection Photos
Operator: BP America
API: 067-07329
Date: 7/23/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the kochia growing within the northeastern project area that needs to be managed (ie mowed).



Photo 3. View of the western fill slope from the northwestern corner facing southward. Revegetation is progressing with rubber rabbitbrush, western wheatgrass, and crested wheatgrass.



Photo 4. View of the southern fill slope from the southwestern corner facing eastward. Musk thistles appear to be recently herbicide-treated.



Photo 5. View of stained soils on the well pad, approximately 3-5 feet long and wide.



Photo 6. View of reference area comprised of sagebrush shrubland and mixed pinyon and juniper woodland.