

Interim Reclamation and Stormwater Inspection

July 28, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 446137

Inspection Document #: 697501800

Weld County, CO

NESE Section 22 T3N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HILGERS /12N-22HZ
Location ID: 446137



Photo 1. Photo taken from the northern location, facing East. Photo illustrates unmanaged weeds.

Inspection Photos
Location Name: HILGERS /12N-22HZ
Location ID: 446137



Photo 2. Photo taken from the northern location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: HILGERS /12N-22HZ
Location ID: 446137



Photo 3. Photo taken from the western location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: HILGERS /12N-22HZ
Location ID: 446137



Photo 4. Photo taken from the western location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: HILGERS /12N-22HZ
Location ID: 446137



Photo 5. Photo taken from the southern location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: HILGERS /12N-22HZ
Location ID: 446137



Photo 6. Photo taken from the southern location, facing East. See comments under Photo 1.