

Interim Reclamation and Stormwater Inspection

July 30, 2020

Operator: PAINTED PEGASUS PETROLEUM LLC - #10711

Location ID: 320095

Inspection Document #: 697501802

Adams County, CO

SWNE Section 8 T1S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PENNY #32-8
Location ID: 320095



Photo 1. COGCC GISOnline aerial imagery taken 2017. Imagery illustrates the associated offsite tank battery (red circle) and a well location (orange circle). This complaint was in regards to the tank battery. COGCC staff also inspected the well location and observed weeds there as well.

Note: The tank battery also services the well directly to the west (001-07967); however, there were no observed reclamation compliance issues.



Inspection Photos
Location Name: PENNY #32-8
Location ID: 320095



Photo 2. Photo taken from the tank battery, facing West. Photo illustrates Operator signs and which wells the tank battery services.

Inspection Photos
Location Name: PENNY #32-8
Location ID: 320095



Photo 3. Photo taken from the northern tank battery, facing South. Photo illustrates unmanaged weeds.



Inspection Photos
Location Name: PENNY #32-8
Location ID: 320095



Photo 4. Photo taken from the central tank battery, facing South. See comments under Photo 3.



Inspection Photos
Location Name: PENNY #32-8
Location ID: 320095



Photo 5. Photo taken from the southwestern tank battery, facing North. See comments under Photo 3.



Inspection Photos
Location Name: PENNY #32-8
Location ID: 320095



Photo 6. Photo taken from the southeastern tank battery, facing West. Photo illustrates weed debris mixed with piled gravel from previous weed management; appears the Operator used a skid-steer to pile up weed debris/gravel. Surface owner can no longer drive mower through this section of land.



Inspection Photos
Location Name: PENNY #32-8
Location ID: 320095



Photo 7. Photo taken from the Penny well location, facing West. Photo illustrates the Operator sign. Note- per Rule 210.e., signs shall be legible. The Operator name is starting to wear.

Inspection Photos
Location Name: PENNY #32-8
Location ID: 320095



Photo 8. Photo taken from the Penny well location, facing South. Photo illustrates a List B Colorado noxious weed, Canada thistle, which has already flowered. Canada thistle can be a very troublesome weed and can spread rapidly via roots and seeds.

