

Inspection Photos
Location Name: Razor 21 SWD 1
Location ID: 440313



Photo 1 – TA Wellhead, weeds

Photo 2 – TA Wellhead, weeds

Inspection Photos
Location Name: Razor 21 SWD 1
Location ID: 440313



Photo 3 – TA Wellhead, weeds



Photo 4 – Wellhead Signage at Entrance not visible