

Inspection Photos
Location Name: PHINNEY-66N64W /10NESE
Location #: 305859



Photo #1

Phinney 43-10 (05-123-23590) Wellsite

Shut-In | SI

Weeds



Photo #2

Phinney 43-10 Wellsite

Shut-In | SI

Weeds: Mitigated

Inspection Photos

Location Name: PHINNEY-66N64W /10NESE

Location #: 305859



Photo #3

Phinney 44-10, 33-10, 34-10, 43-10 Battery site

Inactive | Shut-down

prior insp.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources