

BP L48 San Juan



V2 Compliance Follow Up Form

18149848078

Reference Number:

20200728-18149848078

Form Name:

V2 Compliance Follow Up Form

Submitter Name:

Cole Nichols (colen@horizonenvservices.com) |
colen@horizonenvservices.com

Submission Date:

Jul 28, 2020 7:08:08 AM MDT

Location:

91 S Skylane Dr, Durango, CO 81303, USA
Jul 28, 2020 7:11:32 AM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Jul 27, 2020

Well Name

SMITH WOLTER GAS UNIT 1

API Number

50670723600

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Clean Up Weed Debris

Photo of first corrective action completed



**Completed work description Corrective
Action 1**

Before treatment.

Photo of second corrective action completed**Completed work description of corrective
action 2**

Before treatment.

Photo of third corrective action completed



Completed work description of corrective action 3

Removed thistle seed heads.

Photo of fourth corrective action completed

**Completed work description**

Removed weed debris and treated musk thistle rosetts.

Completed work description of corrective action 4

Removed weed debris and treated musk thistle rosetts.

Additional photos**Additional photos**



Additional photos

**Additional photos****Completed work description**

Removed weed debris and selectively treated musk thistle rosetts.

Summary of all work completed

Dates that previous treatment occurred 6/16/16, 7/13/17, 7/9/18, 6/27/19.