

BP L48 San Juan



V2 Compliance Follow Up Form

18149874361

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200728-18149874361

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Jul 28, 2020 11:43:12 AM MDT

557 Airpark Dr, Durango, CO 81303, USA

Jul 28, 2020 11:42:36 AM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Jul 23, 2020

Well Name

KRAJACK GAS UNIT 43-27 1

Location Name (Other)

krajack 43-27 3, 4

API Number

50670771300

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Seeding

Photo of first corrective action completed



Completed work description Corrective
Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

seeded and blanketed slopes

Photo of third corrective action completed



Completed work description of corrective action 3

seeded and blanketed slopes

Photo of fourth corrective action completed



Completed work description

seeded and blanketed slopes

Completed work description of corrective action 4

seeded and blanketed slopes with erosion issues

Additional photos

**Completed work description**

seeded and blanketed slopes

Summary of all work completedseeded and blanketed slopes using 100%
biodegradable blanket