

BP L48 San Juan



V2 Compliance Follow Up Form

18150151878

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200730-18150151878

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |
colen@horizonenvservices.com

Jul 30, 2020 4:47:40 PM MDT

91 S Skylane Dr, Durango, CO 81303, USA

Jul 30, 2020 4:47:39 PM MDT [[View Map](#)]

INFORMATION

Section 1

| | |
|---|------------------------------|
| Name | colen@horizonenvservices.com |
| Date | Jul 30, 2020 |
| Well Name | ELDRIDGE 25-01 2 |
| API Number | 50670956600 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Clean Up Weed Debris |
| Photo of first corrective action completed | |



Completed work description Corrective removed weeds
Action 1

Photo of second corrective action completed



**Completed work description of corrective
action 2**

removed weed

Photo of third corrective action completed



Completed work description of corrective action 3

removed weed

Photo of fourth corrective action completed



Completed work description of corrective action 4

removed weed

Summary of all work completed

removed and hauled away weeds