Pit Status Evaluation Form

Pit Overview:

Pit Name: **BRINGELSON 15-5 & 16-5** **Facility ID:** **118046**

Current Status: Unknown **Status Date:** 9/23/1999

Current Operator: DIVERSIFIED OPERATING CORPORATION / 24461

Updated Operator: NOBLE ENERGY INC 100322

Form 15 Pit Permit Doc #: **Permit Date:**

Related Facilities: Duplicate pit 112013

County: Weld

Township: 8N **Range:** 58W **Section:** 5 **QQ:** CSE

Original Latitude/ Longitude: 40.687975 / -103.881546

Updated Latitude/ Longitude: 40.685856 / -103.883894

Basis for Location Change:

Moved adjacent to duplicate pit

Pit Inspection/Information Request:

Field Inspection Date: **Document #:**

Pit Still Present in Field: No

Visible Surface Impacts: ☐ **Stressed Vegetation** ☐ **Surface Depression** ☐ **Stained Soil** ☐ **Other (see below)**

Inspection Notes:

Operator Required to Submit Form: NA **Due Date:**

Form Request Sent To: **Sent Date:**

Pit Status Evaluation:

Pit Status Review Documents:

- [ ] **Form 15 Pit Permit – Doc #:** **Date:**
- [ ] **Field Inspection(s) – Doc #:** **Date:**
  - **Doc #:** **Date:**
  - **Doc #:** **Date:**
- [ ] **Form 27 Remediation Workplan – Project #:** **Date:**
- [ ] **Form 4 Sundry Notice – Doc #:** **Date:**
- [ ] **COGIS Document – Doc #:** **Date:**
- [ ] **Pit Inventory – Doc #:** **Date:**
- [x] **Duplicate Record – Duplicate Pit(s) #:** LILLI UNIT 12-4, 15-5, 16-6 112013
- [ ] **Aerial Photo Verification (photos attached)**
- [ ] **Other:**

Pit Status Determination

Updated Pit Status: Closed **Pit Status Date: 12/26/2013**

Timing of Pit Closure:

With duplicate pit

Pit Status Review Summary:

Duplicate Pit #112013 was closed with the following comment "Not related; no docs; GIS map indicates related to well #123-13339 Historic Production Pit closed with REM#7461, ACE for John Axelson, 12/26/2013"

Pit status has been changed to closed NG