

Inspection Photos

7/31/2020

Operator: CHEVRON USA INC - 16700

Location ID: 336051

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 336051



Photo 1: Photo taken from the east end of the Location facing south. Photo shows 1-4 provide an overview of the Location from south, southwest, northwest to north.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 336051



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 336051



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 336051



Photo 4: See comments under photo 1.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 336051



Photo 5: Photo taken from the east end of the Location. Photo shows straw wattles have not been installed or maintained in proper functioning condition.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 336051



Photo 6: Photo taken from the east end of the Location. Photo shows straw wattles have not been installed or maintained in proper functioning condition.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 336051



Photo 7: Photo taken from the ditch on the east end of the Location. Phot shows wattles within ditch; this is now considered debris.