

Inspection Photos
Location Name: Hladky O'Gorman #3
Location ID: 332971



Photo 1 Loc pic Access road blocked by irrigation pip.



Photo 2 Weeds around electric panel

Inspection Photos
Location Name: Hladky O'Gorman #3
Location ID: 332971



Photo 3 WH new sign has been installed



**Photo 4 Operator unused equipment has been removed.
Weeds on location.**

Inspection Photos
Location Name: Hladky O'Gorman #3
Location ID: 332971



Photo 5 Risers have been tagged out. Weeds in and around equipment (meter run)



Photo 6 Weeds around equipment.



Inspection Photos
Location Name: Hladky O'Gorman #3
Location ID: 332971



Photo 7 Weeds inside TNK BTRY containment.



Photo 8 Tank battery sign has been addressed. Weeds in and around TNK BTRY

Inspection Photos
Location Name: Hladky O'Gorman #3
Location ID: 332971



Photo 9 Berm appears to have been repaired but due to farmers sprinkler system containment has filled up and has blown out berm of containment around TNK BTRY. Weeds in and around TNK BTRY.



Photo 10 Weeds in and around location.

Inspection Photos
Location Name: Hladky O'Gorman #3
Location ID: 332971



Photo 11 Weeds in and around HOZ SEP



Photo 12 Appears well head leak has been addressed.