

Inspection Photos
Location Name: Bringelson 6-34-9-58 PAD
Location ID: 434923



Photo 1 – Tank Battery Sign

Photo 2 – Wellheads

Inspection Photos
Location Name: Bringelson 6-34-9-58 PAD
Location ID: 434923



Photo 3 – Tank Battery

Photo 4 – Compressor

Inspection Photos
Location Name: Bringelson 6-34-9-58 PAD
Location ID: 434923



Photo 5 – Unused Walkway/Catwalks on Southside of Location

Photo 6 – Day Tank at Compressor missing Wildlife netting