

**Inspection Photos**  
**Location Name: Bringelson 1-32-9-58 PAD**  
**Location ID: 424273**



**Photo 1 – Pumping Units**

**Photo 2 – Day Tanks at Compressor are missing Wildlife Netting**

**Inspection Photos**  
**Location Name: Bringelson 1-32-9-58 PAD**  
**Location ID: 424273**



**Photo 3 – Unused Loadline and Bucker**

**Photo 4 – Unused Walkways/Catwalks**

**Inspection Photos**  
**Location Name: Bringelson 1-32-9-58 PAD**  
**Location ID: 424273**



**Photo 5 – Debris from old Heater Treater Shelter/Building**

**Photo 6 – Unmarked Risers inside berm**

**Inspection Photos**  
**Location Name: Bringelson 1-32-9-58 PAD**  
**Location ID: 424273**



**Photo 7 – Unmarked Risers, Debris, and unused pipes and fittings**

**Photo 8 – Debris, Unused Equipment and Unmarked Risers**