

Interim Reclamation and Stormwater Inspection

July 30, 2020

Operator: HIGHPOINT OPERATING CORPORATION - #10071

Location ID: 318696

Inspection Document #: 697501820

Weld County, CO

NWSE Section 1 T1N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MARTIN #1
Location ID: 318696



Photo 1. Photo taken east of the location, facing West. Photo illustrates the Operator has failed to perform weed management in compliance with reclamation rules.



Inspection Photos
Location Name: MARTIN #1
Location ID: 318696



Photo 2. Photo taken from the eastern location, facing Northwest. See comments under Photo 1.



Inspection Photos
Location Name: MARTIN #1
Location ID: 318696



Photo 3. Photo taken from the eastern location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: MARTIN #1
Location ID: 318696



Photo 4. Photo taken from the eastern location, facing Southwest. See comments under Photo 1.



Inspection Photos
Location Name: MARTIN #1
Location ID: 318696



Photo 5. Photo taken from the location. Photo illustrates the Operator who is responsible for this location, KPK.



Inspection Photos
Location Name: MARTIN #1
Location ID: 318696



Photo 6. Photo taken from the central location, facing North. See comments under Photo 1.

