

**Inspection Photos**  
**Location Name: Zarlengo B1**  
**Location ID: 320326**



**Pic 1 Some weeds on location recently sprayed.**



**Pic 2**



**Inspection Photos**  
**Location Name: Zarlengo B1**  
**Location ID: 320326**



**Pic 3 Wellhead**



**Pic 4 Stained soil around pump jack motor**

**Inspection Photos**  
**Location Name: Zarlengo B1**  
**Location ID: 320326**



**Pic 5 stained soil under pump jack motor**

