

**Inspection Photos**  
**Spill/Release Name: 16" Pipeline Release**  
**Spill/Release ID: 460855**  
**Inspection Date: July 28, 2020**



**Sign at the access gate for the spill/release area.**



**View of the spill/release area looking south.**



**Inspection Photos**  
**Spill/Release Name: 16" Pipeline Release**  
**Spill/Release ID: 460855**  
**Inspection Date: July 28, 2020**



**Low Cost Ditch looking south.**



**Low Cost Ditch looking north.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Spill/Release Name: 16" Pipeline Release**  
**Spill/Release ID: 460855**  
**Inspection Date: July 28, 2020**



**Storm water BMPs across Low Cost Ditch looking west.**



**Parachute Creek looking south, potential trash in creek bottom (black bucket).**





**Inspection Photos**  
**Spill/Release Name: 16" Pipeline Release**  
**Spill/Release ID: 460855**  
**Inspection Date: July 28, 2020**



**Parachute Creek looking west.**



**Evidence of livestock or wildlife.**