

# *Inspection Photos*

*Loc#335451*

*Operator: Grizzly*

*Inspection Number: 692402387*

*Inspection Date: 7/24/2020*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry. Insert is of equipment left on Location.

July 24, 2020





Photo#2:  
Knapweed in Interim areas.

July 24, 2020





Photo#3:  
BMP needing maintenance; cleanout of debris weeds.

July 24, 2020



Photo#4:  
Anchor Markers, down.



July 24, 2020