

# *Inspection Photos*

*Loc#416197*

*Operator: Grizzly*

*Insp #: 692402388*

*Insp Date: 7/24/2020*



Photo#1:  
Overview of Location to Southwest.

July 24, 2020



Photo#2:  
Vegetation in Interim area; Insert functioning BMPs.

July 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Grizzly Werner Loc#416197





Photo#3:

Localized stained soil at wellhead and at what may be load out area by Tanks.

July 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Grizzly Werner Loc#416197