

# *Inspection Photos*

*Loc#314170*

*Operator: RMNG/Blk Hills*

*Insp#:692402416*

*Insp Date: 7/27/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location.

July 27, 2020





Photo#2:  
BMP, ditch 5/28/20.



Photo#3:  
BMP, ditch 7/27/20; BMP needs maintenance.

July 27, 2020





Photo#4:  
BMP, ditch 5/28/20



Photo#5:  
BMP, ditch 7/27/20; BMP needs maintenance.

July 27, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMTN NG-BLK Hills Wolf Creek Loc#314170





Photo#6:  
Ditch as it slopes to West .

July 27, 2020



Photo#7:  
Subsidence that has developed in ditch; position  
indicated with arrow in Photo#6.





Photo#2:  
BMP, settling pond 5/28/20.



Photo#3:  
BMP, settling pond 7/27/20; BMP needs maintenance.

July 27, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMTN NG-BLK Hills Wolf Creek Loc#314170