

BP L48 San Juan



V2 Compliance Follow Up Form

18150662518

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200805-18150662518

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Aug 5, 2020 1:27:40 PM MDT

238 N Rodeo Dr, Ignacio, CO 81137, USA

Aug 5, 2020 1:24:27 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Aug 4, 2020
Well Name	STATE CD 2 GAS COM
Location Name (Other)	STATE CD 4
API Number	50670851101
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Seeding Erosion Repairs Install Rock Run Down Clean up Operator Debris Clean Up Land Owner Debris Clean Up Weed Debris Grading of Well Pad

Photo of first corrective action completed



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



Completed work description of corrective action 2

Graded location

Photo of third corrective action completed



**Completed work description of corrective
action 3**

Seeded reclaimed area

Photo of fourth corrective action completed



Completed work description

Clean up trash wattles

Completed work description of corrective action 4

Removed weeds

Summary of all work completed

Compliance , graded location, seeded reclaimed area picked up trash and removed old wattles