

Inspection Photos

Location Name: HORN SPRINGS GAS COM 33-33

API#: 05-071-06105

INSP. #: 695103152



Colorado Oil & Gas Conservation Commission
37.21303, -104.78128, 2229.0m, 80°
2020/08/11 14:58:08

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.21298, -104.78114, 2225.0m, 113°
2020/08/11 14:59:19

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: HORN SPRINGS GAS COM 33-33

API#: 05-071-06105

INSP. #: 695103152



**PHOTO 3: UNUSED RISERS JUST SOUTH OF LOCATION.
REMOVE UNUSED RISERS, COMPLY WITH RULE 603.f. CA
DATE 11-11-20.**



**PHOTO 4: UNUSED RISERS UNDER STEEL BOXES NORTHEAST
OF METERHOUSE. REMOVE UNUSED RISERS, COMPLY WITH
RULE 603.f. CA DATE 11-11-20.**

Inspection Photos

Location Name: HORN SPRINGS GAS COM 33-33

API#: 05-071-06105

INSP. #: 695103152



PHOTO 5: UNUSED 1" RISERS NEXT TO WELLHEAD UNDER 2" PRODUCTION LINE. REMOVE UNUSED RISERS, COMPLY WITH RULE 603.f. CA DATE 11-11-20.



PHOTO 6: CLOSER IMAGE OF 1" RISER MENTIONED IN PREVIOUS PHOTO.