

Inspection Photos

Location Name: LARAMIE ENERGY LLC Hawxhurst /17-04 Pad

Location ID: 422420



Photo #1704 from NW corner of location



Photo #1705 Stained soil at wellhead.