

Inspection Photos
Location Name: Calvary Farms 19-L Pad
Location ID: 457976



Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos
Location Name: Calvary Farms 19-L Pad
Location ID: 457976



Photo 3: Wellhead Sign



Photo 4: Stained soil

Inspection Photos
Location Name: Calvary Farms 19-L Pad
Location ID: 457976



Photo 5: Wellhead Sign



Photo 6: Stained soil

Inspection Photos
Location Name: Calvary Farms 19-L Pad
Location ID: 457976



Photo 7: Wellhead Sign



Photo 8: Stained soil

Inspection Photos
Location Name: Calvary Farms 19-L Pad
Location ID: 457976



Photo 9: Unused equipment in tank battery berm



Photo 10: No labeling on tank

Inspection Photos
Location Name: Calvary Farms 19-L Pad
Location ID: 457976



Photo 11: No labeling on tank



Photo 12: No labeling on tank