

Inspection Photos
Location Name: Genesis #3, 9-2
Location ID: 319579



Photo 1: Pumpjack sign



Photo 2: Stained soil removed

Inspection Photos
Location Name: Genesis #3, 9-2
Location ID: 319579



Photo 3: Unused equipment



Photo 4: Pumpjack sign

Inspection Photos
Location Name: Genesis #3, 9-2
Location ID: 319579



Photo 5: Stained soil



Photo 6: Tank Battery Sign

Inspection Photos
Location Name: Genesis #3, 9-2
Location ID: 319579




Photo 7: Berm repaired



Photo 8: Berm repaired



Inspection Photos
Location Name: Genesis #3, 9-2
Location ID: 319579



Photo 9: Equipment removed



Photo 10: Tank not grounded

