

**Inspection Photos**  
**Operator: BP America**  
**API: 067-07158**  
**Date: 8/11/2020**



Photo 1. View of the eastern project area from the northwestern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with smooth brome, sand dropseed, and western wheatgrass.



Photos 3. View of the northern project area from the northeastern project area facing westward.



Photos 4. View of musk thistles within the southeastern project area. Approximately 100 individuals observed.



Photo 5. View of reference area comprised of pinyon juniper woodland/gambel oak shrubland with understory of western wheatgrass, Arizona fescue, and *Heterotheca villosa*.