

# Inspection Photos

8/13/2020

Operator: EAGLE OPERATING INC - 26155

Location ID: 397838

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: EAGLE OPERATING INC - 26155  
Location ID: 397838



**Photo 1:** Photo taken from the north end of the Location, facing south. Photo shows areas off the access road that were utilized for access the location. Erosion degradation evident.





Inspection Photos  
Operator Name: EAGLE OPERATING INC - 26155  
Location ID: 397838



**Photo 2:** Continued from photo 1.





Inspection Photos  
Operator Name: EAGLE OPERATING INC - 26155  
Location ID: 397838



**Photo 3:** Photo taken from the Location, facing south. Photo show utility equipment has been removed.





## Inspection Photos

Operator Name: EAGLE OPERATING INC - 26155

Location ID: 397838



**Photo 4:** Photo taken from the west end of the Location, facing east. Photo shows areas that appears to have been disturbed during work. Additional disturbance do not appear to have been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: EAGLE OPERATING INC - 26155

Location ID: 397838



**Photo 5:** Photo taken from the Location. Photo shows Halogeton establishment on the Location. This is a Colorado State Listed noxious weed that requires management.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources