

Inspection Photos

API: 017-07813

Operator: MCCOY PETROLEUM CORPORATION

Inspection Date: 8/11/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 017-07813 | Date: 8/11/2020

Inspection Photos



Photo 1. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07813 | Date: 8/11/2020

Inspection Photos



Photo 2. The pit has been backfilled and soil piles have been recontoured.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07813 | Date: 8/11/2020

Inspection Photos



Photo 3. The soils appear to have been decompacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07813 | Date: 8/11/2020