

FORM
5A

Rev
06/12

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

402386593

Date Received:

05/12/2020

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 100322

2. Name of Operator: NOBLE ENERGY INC

3. Address: 1001 NOBLE ENERGY WAY

City: HOUSTON

State: TX

Zip: 77070

4. Contact Name: Craig Richardson

Phone: (303) 228-4232

Fax:

Email: Denverregulatory@nblenergy.com

5. API Number 05-123-18368-00

7. Well Name: D.L. PHILLIPS

6. County: WELD

Well Number: 24-21

8. Location: QtrQtr: NENW

Section: 24

Township: 5N

Range: 67W

Meridian: 6

9. Field Name: WATTENBERG

Field Code: 90750

Completed Interval

FORMATION: CODELL

Status: TEMPORARILY ABANDONED

Treatment Type:

Treatment Date:

End Date:

Date of First Production this formation: 08/10/1994

Perforations

Top: 7437

Bottom: 7447

No. Holes: 80

Hole size: 2 + 1/2

Provide a brief summary of the formation treatment:

Open Hole: ☐

This formation is commingled with another formation:

☐ Yes ☒ No

Total fluid used in treatment (bbl):

Max pressure during treatment (psi):

Total gas used in treatment (mcf):

Fluid density at initial fracture (lbs/gal):

Type of gas used in treatment:

Min frac gradient (psi/ft):

Total acid used in treatment (bbl):

Number of staged intervals:

Recycled water used in treatment (bbl):

Flowback volume recovered (bbl):

Fresh water used in treatment (bbl):

Disposition method for flowback:

Total proppant used (lbs):

Rule 805 green completion techniques were utilized: ☐

Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: Hours: Bbl oil: Mcf Gas: Bbl H2O:

Calculated 24 hour rate: Bbl oil: Mcf Gas: Bbl H2O: GOR:

Test Method: Casing PSI: Tubing PSI: Choke Size:

Gas Disposition: Gas Type: Btu Gas: API Gravity Oil:

Tubing Size: Tubing Setting Depth: Tbg setting date: Packer Depth:

Reason for Non-Production: Surface Equipment removed on 8/2/2018.

Date formation Abandoned: 08/02/2018 Squeeze: ☐ Yes ☐ No If yes, number of sacks cmt

** Bridge Plug Depth: ** Sacks cement on top: ** Wireline and Cement Job Summary must be attached.

Comment:

This well is TA because surface equipment was removed due to LTSI. There are no plugs downhole.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Julie Webb

Title: Sr. Regulatory Analyst

Date: 5/12/2020

Email: julie.webb@nblenergy.com

:

Attachment Check List

Att Doc Num

Name

402386593

FORM 5A SUBMITTED

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

Permit

Permitting review complete.

08/14/2020

Total: 1 comment(s)