

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/10/2020

Submitted Date:

08/10/2020

Document Number:

699102242

FIELD INSPECTION FORM

Loc ID 336618 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:
OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
8 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245902	WELL	SI	04/01/2019	GW	123-13697	GEMINI B29-5	PA
295169	WELL	TA	07/01/2019	GW	123-25680	FAIRBANKS B 29-31	TA

General Comment:
[Facility is decommissioned.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 245902 Type: WELL API Number: 123-13697 Status: SI Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: P/A, Subsequent Report of Abandonment, Form, 6.

Corrective Action: Within 30 days after abandonment, the Well Abandonment Report, Form 6 - Subsequent Report of Abandonment, shall be filed with the Director. Date: 09/10/2020

Facility ID: 295169 Type: WELL API Number: 123-25680 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: T/A

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 8/10/20 at approximately 1005hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Gemini B29-5 & Fairbanks B 29-31 of Noble Energy, at Location ID # 336618 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Subsequent Report of Abandonment, Form, 6. Within 30 days after abandonment, the Well Abandonment Report, Form 6 - Subsequent Report of Abandonment, shall be filed with the Director comply with rule 311.b. With a corrective action date of 9/10/20. See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing education inspections</p>	burnsa	08/10/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402462909	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5220203
699102243	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5220200