

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/07/2020

Submitted Date:

08/10/2020

Document Number:

700600135**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Kosola, Jason 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 61250Name of Operator: MULL DRILLING COMPANY INCAddress: 1700 N WATERFRONT PKWY B#1200City: WICHITA State: KS Zip: 67206-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beilman, James	316-734-8108	JBeilman@mulldrilling.com	<a href="#">Environmental/Safety Manager</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150039	UIC DISPOSAL	AC	11/29/1983		-	PELTON SWDW TWIN 1	AC

**General Comment:**

Operator shall conduct investigation into the extent of release of fluids to include obtaining soil samples and visual investigation.

Operator shall submit Form 19 Subsequent within 10 days of spill. Confirmation soil samples should be submitted via Form 19 Supplemental. Multiple Form 19 Subsequents may need to be submitted to address spill impacts.

Tank battery shall be reconstructed with steel ring containment and synthetic liner.



**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: 5

Comment: Spill at tank battery as a result of a fire caused by lightening strike.

Corrective Action: Submit Form 19 Initial within 72 hours as required per rule.

Date: 08/10/2020

Reportable: YES

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

**Water Well Complaint:**

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

**Field Parameters:**

Sample Location:

Comment:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402462963	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5220246">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5220246</a>
700600136	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5220242">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5220242</a>