

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/05/2020

Submitted Date:

08/10/2020

Document Number:

701100166

FIELD INSPECTION FORM

Loc ID 335699	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				Findings: 15 Number of Comments 5 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Katz, Aaron		aaron.katz@state.co.us	
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
, Engineering		dnr_cogccengineering@state.co.us	All engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287610	WELL	TA	02/04/2019	GW	045-13007	N. PARACHUTE CP14A-09 G09 59	TA
287621	WELL	TA	02/04/2019	GW	045-13006	N. PARACHUTE CP07B-09 G09 59	TA
287624	WELL	TA	02/04/2019	GW	045-13004	N. PARACHUTE CP02D-09 G09 59	TA
291109	WELL	TA	02/04/2019	GW	045-14297	N.PARACHUTE CP11B-09 G09 596	TA
454313	WELL	XX	03/14/2018		045-23860	NPR 12C-9-596	ND
454314	WELL	XX	03/14/2018		045-23861	NPR 21B-9-596	ND
454315	WELL	XX	03/14/2018		045-23862	NPR 22B-9-596	ND
454316	WELL	XX	03/14/2018		045-23863	NPR 22D-9-596	ND
454317	WELL	XX	03/14/2018		045-23864	NPR 14B-9-596	ND
454318	WELL	XX	03/14/2018		045-23865	NPR 21C-9-596	ND
454319	WELL	XX	03/14/2018		045-23866	NPR 11B-9-596	ND
454320	WELL	XX	03/14/2018		045-23867	NPR 12D-9-596	ND
454321	WELL	XX	03/14/2018		045-23868	NPR 12B-9-596	ND
454322	WELL	XX	03/14/2018		045-23869	NPR 13D-9-596	ND
454323	WELL	XX	03/14/2018		045-23870	NPR 14C-9-596	ND
454324	WELL	XX	03/14/2018		045-23871	NPR 13A-9-596	ND

454325	WELL	XX	03/14/2018		045-23872	NPR 22A-9-596	ND
454326	WELL	PR	05/24/2019	GW	045-23873	NPR 11C-9-596	PR
454327	WELL	PR	05/26/2019	GW	045-23874	NPR 11D-9-596	PR
454328	WELL	XX	03/14/2018		045-23875	NPR 13B-9-596	ND
454329	WELL	PR	04/01/2020	GW	045-23876	NPR 11A-9-596	PR
454330	WELL	DG	02/18/2019		045-23877	NPR 21A-9-596	ND
454331	WELL	PR	05/25/2019	GW	045-23878	NPR 12A-9-596	PR
454332	WELL	XX	03/14/2018		045-23879	NPR 24A-9-596	ND
454333	WELL	XX	03/14/2018		045-23880	NPR 23B-9-596	ND
454334	WELL	PR	05/22/2019	GW	045-23881	NPR 25D-4-596	PR
454335	WELL	XX	03/14/2018		045-23882	NPR 23D-9-596	ND
454336	WELL	XX	03/14/2018		045-23883	NPR 23C-9-596	ND
454337	WELL	XX	03/14/2018		045-23884	NPR 23A-9-596	ND
454338	WELL	XX	03/14/2018		045-23885	NPR 24B-9-596	ND
454339	WELL	PR		GW	045-23886	NPR 25C-4-596	WK
454353	WELL	XX	03/15/2018		045-23887	NPR 14A-9-596	ND

General Comment:

During this inspection the following possible compliance issues were observed:

Temporarily abandoned wells need updated per Form 4 COA's

Contact COGCC Engineering Staff

C.A. Date 8/21/2020

No battery sign.

Install sign to comply with Rule 210.b.

C.A. Date 11/11/2020

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	11/11/2020
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 335699 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective
Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 287610 Type: WELL API Number: 045-13007 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Temp. abandoned since August 2018
Form 4 doc# 401928418
Well temporarily abandoned to allow drilling rig on site.
COA from Form 4
"This approval is good for one year and a new application must be made before February 4, 2020 (1 year from prior application). Updates for the planned utilization of the well should be included with the application."

Corrective Action: Contact COGCC Engineering Staff Date: 08/21/2020

Facility ID: 287621 Type: WELL API Number: 045-13006 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Temp. abandoned since August 2018
Form 4 doc# 401928993
Well temporarily abandoned to allow drilling rig on site.
COA from Form 4
"This approval is good for one year and a new application must be made before 2/4/2020 (1 year from prior application). Updates for the planned utilization of the well should be included with the application. Provide further details on when the location will become available."

Corrective Action: Contact COGCC Engineering staff. Date: 08/21/2020

Facility ID: 287624 Type: WELL API Number: 045-13004 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Temp. abandoned since August 2018
Form 4 doc# 401928580
COA from Form 4
"This approval is good for one year and a new application must be made before February 4, 2020 (1 year from prior application). Updates for the planned utilization of the well should be included with the application."

Corrective Action: Contact COGCC Engineering staff. Date: 08/21/2020

Facility ID: 291109 Type: WELL API Number: 045-14297 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Temp. abandoned since August 2018
Form 4 doc# 401928475
COA from Form 4
"This approval is good for one year and a new application must be made before February 4, 2020 (1 year from prior application). Updates for the planned utilization of the well should be included with the application."

Corrective Action: Contact COGCC Engineering staff. Date: 08/21/2020

Facility ID: 454313 Type: WELL API Number: 045-23860 Status: XX Insp. Status: ND

Facility ID: 454314 Type: WELL API Number: 045-23861 Status: XX Insp. Status: ND

Facility ID:	454315	Type:	WELL	API Number:	045-23862	Status:	XX	Insp. Status:	ND
Facility ID:	454316	Type:	WELL	API Number:	045-23863	Status:	XX	Insp. Status:	ND
Facility ID:	454317	Type:	WELL	API Number:	045-23864	Status:	XX	Insp. Status:	ND
Facility ID:	454318	Type:	WELL	API Number:	045-23865	Status:	XX	Insp. Status:	ND
Facility ID:	454319	Type:	WELL	API Number:	045-23866	Status:	XX	Insp. Status:	ND
Facility ID:	454320	Type:	WELL	API Number:	045-23867	Status:	XX	Insp. Status:	ND
Facility ID:	454321	Type:	WELL	API Number:	045-23868	Status:	XX	Insp. Status:	ND
Facility ID:	454322	Type:	WELL	API Number:	045-23869	Status:	XX	Insp. Status:	ND
Facility ID:	454323	Type:	WELL	API Number:	045-23870	Status:	XX	Insp. Status:	ND
Facility ID:	454324	Type:	WELL	API Number:	045-23871	Status:	XX	Insp. Status:	ND
Facility ID:	454325	Type:	WELL	API Number:	045-23872	Status:	XX	Insp. Status:	ND
Facility ID:	454326	Type:	WELL	API Number:	045-23873	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	454327	Type:	WELL	API Number:	045-23874	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	454328	Type:	WELL	API Number:	045-23875	Status:	XX	Insp. Status:	ND
Facility ID:	454329	Type:	WELL	API Number:	045-23876	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID: 454330	Type: WELL	API Number: 045-23877	Status: DG	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Facility ID: 454331	Type: WELL	API Number: 045-23878	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 454332	Type: WELL	API Number: 045-23879	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Facility ID: 454333	Type: WELL	API Number: 045-23880	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Facility ID: 454334	Type: WELL	API Number: 045-23881	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 454335	Type: WELL	API Number: 045-23882	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Facility ID: 454336	Type: WELL	API Number: 045-23883	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Facility ID: 454337	Type: WELL	API Number: 045-23884	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Facility ID: 454338	Type: WELL	API Number: 045-23885	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Facility ID: 454339	Type: WELL	API Number: 045-23886	Status: PR	Insp. Status: WK
---------------------	------------	-----------------------	------------	------------------

Workover

Comment: Form 42 (402461857) received hour and 45 minutes after planned start time. Notice does not meet the 48 hour notice requirement. Caerus staff was notified at the time of the late notice being received.
Duco rig and cement service equipment on well. No crew present at time of inspection.

Corrective Action:

Date:

Facility ID: 454353	Type: WELL	API Number: 045-23887	Status: XX	Insp. Status: ND
---------------------	------------	-----------------------	------------	------------------

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402462678	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5219977
701100174	Inspection 701100166 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5219976