

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/07/2020

Submitted Date:

08/10/2020

Document Number:

701100168

FIELD INSPECTION FORM

Loc ID 457122	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				Findings: 3 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457099	WELL	XX	08/31/2018		045-24039	NPR 25A-17-596	ND
457100	WELL	XX	08/31/2018		045-24040	NPR 11A-21-596	ND
457101	WELL	XX	08/31/2018		045-24041	Chevron 41A-20-596	ND
457102	WELL	XX	08/31/2018		045-24042	Chevron 41C-20-596	ND
457103	WELL	XX	08/31/2018		045-24043	NPR 15A-16-596	ND
457104	WELL	XX	08/31/2018		045-24044	Chevron 42D-20-596	ND
457105	WELL	XX	08/31/2018		045-24045	Chevron 41D-20-596	ND
457106	WELL	XX	08/31/2018		045-24046	NPR 14D-16-596	ND
457107	WELL	XX	08/31/2018		045-24047	Chevron 42A-20-596	ND
457108	WELL	XX	08/31/2018		045-24048	NPR 11B-21-596	ND
457109	WELL	XX	08/31/2018		045-24049	Chevron 42B-20-596	ND
457110	WELL	XX	08/31/2018		045-24050	NPR 15D-16-596	ND
457111	WELL	XX	08/31/2018		045-24051	Chevron 41B-20-596	ND
457112	WELL	XX	08/31/2018		045-24052	NPR 25D-17-596	ND
457113	WELL	XX	08/31/2018		045-24053	NPR 15B-16-596	ND
457114	WELL	XX	08/31/2018		045-24054	NPR 25B-17-596	ND
457115	WELL	XX	08/31/2018		045-24055	NPR 24C-17-596	ND
457116	WELL	XX	08/31/2018		045-24056	NPR 24B-17-596	ND
457117	WELL	XX	08/31/2018		045-24057	NPR 15C-16-596	ND
457118	WELL	XX	08/31/2018		045-24058	NPR 14C-16-596	ND

457119	WELL	XX	08/31/2018		045-24059	NPR 24D-17-596	ND
457120	WELL	XX	08/31/2018		045-24060	NPR 25C-17-596	ND
457121	WELL	XX	08/31/2018		045-24061	NPR 11C-21-596	ND
457123	WELL	XX	08/31/2018		045-24062	NPR 11D-21-596	ND
457124	WELL	XX	08/31/2018		045-24063	Chevron 42C-20-596	ND

General Comment:

During this inspection the following possible compliance issues were observed:

No location sign

Comply with Rule 305.g.

Date: 11/11/2020

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	No location sign		
Corrective Action:	Comply with Rule 305.g.	Date:	11/11/2020

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>457099</u>	Type: <u>WELL</u>	API Number: <u>045-24039</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457100</u>	Type: <u>WELL</u>	API Number: <u>045-24040</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457101</u>	Type: <u>WELL</u>	API Number: <u>045-24041</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457102</u>	Type: <u>WELL</u>	API Number: <u>045-24042</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457103</u>	Type: <u>WELL</u>	API Number: <u>045-24043</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457104</u>	Type: <u>WELL</u>	API Number: <u>045-24044</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457105</u>	Type: <u>WELL</u>	API Number: <u>045-24045</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457106</u>	Type: <u>WELL</u>	API Number: <u>045-24046</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457107</u>	Type: <u>WELL</u>	API Number: <u>045-24047</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457108</u>	Type: <u>WELL</u>	API Number: <u>045-24048</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457109</u>	Type: <u>WELL</u>	API Number: <u>045-24049</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457110</u>	Type: <u>WELL</u>	API Number: <u>045-24050</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457111</u>	Type: <u>WELL</u>	API Number: <u>045-24051</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457112</u>	Type: <u>WELL</u>	API Number: <u>045-24052</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457113</u>	Type: <u>WELL</u>	API Number: <u>045-24053</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457114</u>	Type: <u>WELL</u>	API Number: <u>045-24054</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457115</u>	Type: <u>WELL</u>	API Number: <u>045-24055</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457116</u>	Type: <u>WELL</u>	API Number: <u>045-24056</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>457117</u>	Type: <u>WELL</u>	API Number: <u>045-24057</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>

Facility ID:	457118	Type:	WELL	API Number:	045-24058	Status:	XX	Insp. Status:	ND
Facility ID:	457119	Type:	WELL	API Number:	045-24059	Status:	XX	Insp. Status:	ND
Facility ID:	457120	Type:	WELL	API Number:	045-24060	Status:	XX	Insp. Status:	ND
Facility ID:	457121	Type:	WELL	API Number:	045-24061	Status:	XX	Insp. Status:	ND
Facility ID:	457123	Type:	WELL	API Number:	045-24062	Status:	XX	Insp. Status:	ND
Facility ID:	457124	Type:	WELL	API Number:	045-24063	Status:	XX	Insp. Status:	ND

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts	Pass					
		Ditches	Pass			
		Culverts	Pass			
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402462709	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5220011
701100175	Inspection 701100168 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5220009