

Inspection Photos

Location Name: LAGARITA 42-20 WD

API#: 05-071-07045

INSP. #: 695103158



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos




PHOTO 3: INJECTION PRESSURE GAUGE.



PHOTO 4: T-C ANNULUS PRESSURE GAUGE.

Inspection Photos



PHOTO 5: BRADENHEAD PRESSURE GAUGE.