

# Inspection Photos

Location Name: BLUESKY 44-17

API#: 05-071-08511


INSP. #: 695103160



**PHOTO 1: LOCATION**

**PHOTO 2: WELL SIGN**

Inspection Photos  
 Location Name: BLUESKY 44-17  
 API#: 05-071-08511  
 INSP. #: 695103160



**PHOTO 3: NO CURRENT CALIBRATION ON GAS METER.**  
 Provide calibration records or calibrate meter as required by Rule 329. CA DATE 9-12-20.

**PHOTO 4: UNUSED EQUIPMENT (GAS ENGINE SKID IS NOT CONNECTED). REMOVE UNUSED EQUIPEMNT OR PUT EQUIPMENT INTO USE, COMPLY WITH RULE 603.f. CA DATE 11-12-20.**

Inspection Photos  
Location Name: BLUESKY 44-17  
API#: 05-071-08511  
INSP. #: 695103160



**PHOTO 5: NO FREEBOARD MARKER IN PRODUCED WATER  
PIT. INSTALL FREEBOARD MARKER, COMPLY WITH RULE  
902.b. CA DATE 11-12-20.**