

**Inspection Photos**  
**Location Name: VPR C NO. 29**  
**API#: 05-071-06931**  
**INSP. #: 695103168**



Colorado Oil & Gas Conservation Commission  
37.15436, -105.01966, 36°  
2020/08/18 13:21:46



Colorado Oil & Gas Conservation Commission  
37.00087, -104.78865, 2368.0m, 99°  
2020/08/18 13:22:29

**PHOTO 1: LOCATION**

**PHOTO 2: WELL SIGN**

Inspection Photos  
Location Name: VPR C NO. 29  
API#: 05-071-06931  
INSP. #: 695103168



**PHOTO 3: AREA OF IMPACTED SOIL AROUND WELLHEAD. REMOVE IMPACTED SOIL, Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. CA DATE 11-18-20.**

**PHOTO 4: BRADENHEAD IS NOT PLUMBED TO SURFACE. PLUMB BRADENHEAD TO SURFACE, COMPLY WITH RULE 608e. CA DATE 11-18-20.**